

PROBEYE INFRARED VIEWER INSTRUCTIONS FOR DC TO DC CHARGING ADAPTER

643D4108

- Insert black plastic connector into vehicle cigarette lighter socket.
- 2. Insert blue connector into PROBEYE Infrared Viewer battery charger socket.
- 3. With vehicle engine off, charging time is the same as the A.C. plug-in charger, I.E. 16 hours, or four hours for every hour used. With vehicle engine running, charging time is half as much.

CAUTION

INSTALL IN VEHICLE WITH 12VDC NEGATIVE GROUND SYSTEM ONLY.